



# Ship Check AI

Delivered by

MARITIME  
DAO




# Captain's Weekly Inspection Instruction

# How to create report

Instruction Rev.1

Do the Inspection,

Make photos.



## Category breakdown:

- Accommodation and recreational facilities
- Ventilation and heating
- Lightning
- Sleeping rooms
- Mess rooms
- Sanitary accommodation
- Laundry
- Mosquito devices
- Recreational facilities, amenities and services
- Hospital accommodation
- Food and catering
- Fresh Water Management

# Create Account + Check e-mail + Verify

## Get started weekly inspection

Vessel name      IMO number      Flag

Inspector name      Inspector rank

Drop up to 100 Images  
or click to select (50-100 recommended)

Start Upload & Analyze

Inspection ID (optional)      Pick Latest      Generate Report (Addon)

**Create account**      Log in

**ShipCheckAI**



## Create account

Username: CaptainRelax 

Email: beachinoffice@gmail.com 

Password: woxKuj-0gokzu-vevr  Strong Password

**Register**

Check your email to activate your account.  
We will email you an activation link. You must confirm it to access your account.

# Fill out DATA + upload inspection photos

## Get started weekly inspection

MV Best in Class      1234567      MI

Captain Relax      MM


Drop up to 100 images  
or click to select (50-100 recommended)

IMG\_3748.jpg      IMG\_3750.jpg      IMG\_3751.jpg



IMG\_3760.jpg

**Start Upload & Analyze**  

Inspection ID (optional)      Pick Latest      Generate Report (Addon)



# Inspection ID - press “Pick Latest”



# Press Generate Report + Download Report

## Get started weekly inspection

MV Best in Class    1234567    MI

Captain Relax    MM

Drop up to 100 Images  
or click to select (50-100 recommended)




- IMG\_3748.jpg (GREEN)
- IMG\_3750.jpg (GREEN)
- IMG\_3751.jpg (GREEN)
- IMG\_3760.jpg (YELLOW)

**Start Upload & Analyze**

0e9cabcf-7414-47c7-987d-0292ce9e6035

**Pick Latest**   **Generate Report (Addon)**



## ShipCheck Weekly Inspection Report

**Vessel:** MV Best in Class **IMO:** 1234567 **Flag:** MI

**Inspector:** Captain Relax

**Position:** N/A

**Rank:** MM

**Final Verdict:** YELLOW

ID	Item	Status	Details
GS-01	Escape routes & doors unobstructed	YELLOW	Issue: Deficiency detected at: Escape routes & doors unobstructed Recommendation: Investigate, rectify, and verify according to referenced regulations. References: ISM Code 10
GS-02	Emergency lighting in key spaces	GREEN	
GS-03	Safety signage & muster lists	GREEN	
GS-04	Watertight/Weathertight doors functional	GREEN	References: SOLAS II-1
GS-05	Housekeeping (decks clean; spill kits)	GREEN	

# Improve what is needed + register in log book

## ShipCheck Weekly Inspection Report

**Vessel:** MV Best in Class **IMO:** 1234567 **Flag:** MI


**Inspector:** Captain Relax

**Position:** N/A

**Rank:** MM

**Final Verdict:** YELLOW

ID	Item	Status	Details
GS-01	Escape routes & doors unobstructed	YELLOW	<p>Issue: Deficiency detected at: Escape routes &amp; doors unobstructed</p> <p>Recommendation: Investigate, rectify, and verify according to referenced regulations.</p> <p>References: ISM Code 10</p>
GS-02	Emergency lighting in key spaces	GREEN	
GS-03	Safety signage & muster lists	GREEN	
GS-04	Watertight/Weathertight doors functional	GREEN	References: SOLAS II-1
GS-05	Housekeeping (decks clean; spill kits)	GREEN	



**ShipCheckAI**